

## LEGEND

| М    | MEASURED                |
|------|-------------------------|
| RP   | RECORD PLAT             |
| FIRC | FOUND IRON ROD          |
|      | AND CAP                 |
| SIRC | SET IRON ROD &          |
|      | CAP #7160-5/8"          |
| FIR  | FOUND IRON ROD          |
| FIP  | FOUND IRON PIPE         |
| R/W  | RIGHT-OF-WAY            |
| ₩-   | NOT TO SCALE            |
| ٨    | POINT NOT SET           |
|      | OR FOUND                |
| d    | POWER POLE              |
| Ľ    |                         |
| OHE  | OVERHEAD ELECTRIC LINES |
| <    | GUY WIRE ANCHOR         |

SEWER MANHOLE

SEWER CLEANOUT/ SERVICE

- 1. SURVEY SOURCE: Record plat and a field survey performed by
- 2. BEARING REFERENCE: Northwesterly right of way boundary of Mississippi Drive having an assumed bearing of South 40 degrees
- 3. NO IMPROVEMENTS have been located in this survey other than
- There are NO VISIBLE ENCROACHMENTS other than those shown
- 5. This survey is dependent upon EXISTING MONUMENTATION.
- 6. Not valid without the signature and the original raised seal of a Florida licensed surveyor and mapper.
- 7. FLOOD ZONES and SETBACKS depicted hereon are not to be used for construction permitting purposes. All FLOOD ZONES and SETBACKS should be verified by the appropriate County

Subject property is located in Zone "X" as per Flood Insurance Rate Map Community Panel No: 120010 0517H

## PRELIMINARY FLOOD ZONE INFORMATION:

Subject property is located in Zone "X-0.2%" as per Flood Insurance Rate Map Community Panel No: 120010 0509J index date: October 25, 2019, Bay County, Florida.

