

2 Surveys Put Together



CERTIFICATION	SURVEY REPORT: TI-17012	PROPERTY LOCATION:
I, the undersigned, do hereby certify, that this plat was prepared from the findings of a survey, made on the ground and under my supervision, of the property shown. This plat shall only be used in accordance with the Terms and Conditions of the associate notes, being part of this report.	Plat of Survey Part One	South of Alexander Road Titus County, Texas
Scale: 1" = 40'	July 19th, 2017	The metes and bounds description of this property is contained in the associated Field Notes, being Part Two of this report.
Legend		
<ul style="list-style-type: none"> ⊙ - 1/2" Capped Steel Rod Set ⊕ - 1/2" Capped Steel Rod Fnd ⊙ - 1/2" Steel Rod Found 	<ul style="list-style-type: none"> ⊙ - 5/8" Steel Rod Fnd ⊕ - 3/8" Steel Rod Fnd ⊙ - Air Conditioner 	<ul style="list-style-type: none"> ⊙ - Steel Pipe Found ⊕ - 602 Nail Found ⊙ - 604 Nail Set ⊙ - Fence Corner Post ⊕ - Gas Meter ⊙ - Electric Box ⊕ - Septic System ⊕ - Electric Meter ⊕ - GAS - Gas Pipe Line