

I, Justin Kleam RPLS No. 5871, do hereby certify to: Ann Karralis, as attach. That the Plat of Survey shown hereon is a correct and accurate representation of the property lines and dimensions are as indicated; the location and type of buildings are as shown; and EXCEPT AS SHOWN, all improvements are located within the boundaries the distances indicated and there are no visible and apparent encroachments or protrusions on the ground. Use of this survey by any other parties and/or for other purposes shall be at user's own risk and any loss resulting from other use shall not be the responsibility of the undersigned.

SURVEYOR'S NOTES:
1) BEARINGS ARE BASED ON A POINT FOR CORNER IN A 30 INCH WHITE OAK TREE FOUND AT A NORTHEAST CORNER OF A TRACT OF LAND, AS DESCRIBED IN FILE #20130000833, R.P.R.T.C.T., THENCE S07°43'37"E A DISTANCE OF 1,340.55', TO A POINT FOR CORNER AT THE SOUTHEAST CORNER OF SAID TRACT.
2) NO EASEMENT RECORD SEARCH WAS MADE BY THIS OFFICE CONCERNING THIS PROPERTY.
3) NO FLOOD INFORMATION WAS RESEARCHED REGARDING THIS TRACT.
4) SEE LEGAL DESCRIPTIONS THIS EVEN DATE AND JOB NUMBER.

ESG SURVEYORS INC.
1455 HILLCREST DRIVE
MOUNT PLEASANT, TEXAS 75462
PHONE: (903) 435-1200
FAX: (903) 435-1269
esgsurveyors.com